

# SHEETS 1000X1000 MM.

| ◆ Thickness MM. | ◆ Thickness Tolerance MM. | ◆ Size Tolerance MM. |
|-----------------|---------------------------|----------------------|
| 1               | +/-0,050                  | +30/-0               |
| 1,5             | +/-0,050                  | +30/-0               |
| 2               | +/-0,100                  | +30/-0               |
| 2,5             | +/-0,125                  | +30/-0               |
| 3               | +/-0,150                  | +30/-0               |
| 4               | +/-0,40                   | +30/-0               |
| 4,5             | +/-0,40                   | +30/-0               |
| 5               | +/-0,40                   | +30/-0               |
| 6               | +/-0,40                   | +30/-0               |
| 8               | +/-0,60                   | +30/-0               |
| 10              | +/-0,60                   | +30/-0               |
| 12              | +/-1,00                   | +30/-0               |
| 15              | +/-1,00                   | +30/-0               |
| 20              | +/-1,00                   | +30/-0               |
| 25              | +/-1,00                   | +30/-0               |
| 30              | +/-1,50                   | +30/-0               |
| 35              | +/-1,50                   | +30/-0               |
| 40              | +/-1,50                   | +30/-0               |
| 45              | +/-1,50                   | +30/-0               |
| 50              | +/-1,50                   | +30/-0               |
| 60              | +/-1,50                   | +30/-0               |
| 70              | +/-1,50                   | +30/-0               |
| 80              | +/-1,50                   | +30/-0               |

# SHEETS 1200X1200 MM.

| ◆ Thickness MM. | ◆ Thickness Tolerance MM. | ◆ Size Tolerance MM. |
|-----------------|---------------------------|----------------------|
| 1               | +/-0,050                  | +40/-0               |
| 1,5             | +/-0,050                  | +40/-0               |
| 2               | +/-0,100                  | +40/-0               |
| 2,5             | +/-0,125                  | +40/-0               |
| 3               | +/-0,150                  | +40/-0               |
| 4               | +/-0,40                   | +40/-0               |
| 4,5             | +/-0,40                   | +40/-0               |
| 5               | +/-0,40                   | +40/-0               |
| 6               | +/-0,40                   | +40/-0               |
| 8               | +/-0,60                   | +40/-0               |
| 10              | +/-0,60                   | +40/-0               |
| 12              | +/-1,00                   | +40/-0               |
| 15              | +/-1,00                   | +40/-0               |
| 16              | +/-1,00                   | +40/-0               |
| 20              | +/-1,00                   | +40/-0               |
| 25              | +/-1,00                   | +40/-0               |
| 30              | +/-1,50                   | +40/-0               |
| 35              | +/-1,50                   | +40/-0               |
| 40              | +/-1,50                   | +40/-0               |
| 45              | +/-1,50                   | +40/-0               |
| 50              | +/-1,50                   | +40/-0               |
| 60              | +/-1,50                   | +40/-0               |
| 70              | +/-1,50                   | +40/-0               |
| 80              | +/-1,50                   | +40/-0               |
| 90              | +/-2,50                   | +40/-0               |
| 100             | +/-2,50                   | +40/-0               |

# SHEETS 1500X1500 MM.

| Thickness MM. | Thickness Tolerance MM. | Size Tolerance MM. |
|---------------|-------------------------|--------------------|
| 1             | +/-0,050                | +40/-0             |
| 1,5           | +/-0,050                | +40/-0             |
| 2             | +/-0,100                | +40/-0             |
| 2,5           | +/-0,125                | +40/-0             |
| 3             | +/-0,150                | +40/-0             |
| 4             | +/-0,40                 | +40/-0             |
| 4,5           | +/-0,40                 | +40/-0             |
| 5             | +/-0,40                 | +40/-0             |
| 6             | +/-0,40                 | +40/-0             |
| 8             | +/-0,60                 | +40/-0             |
| 10            | +/-0,60                 | +40/-0             |
| 12            | +/-1,00                 | +40/-0             |
| 15            | +/-1,00                 | +40/-0             |
| 20            | +/-1,00                 | +40/-0             |
| 25            | +/-1,00                 | +40/-0             |
| 30            | +/-1,50                 | +40/-0             |
| 35            | +/-1,50                 | +40/-0             |
| 40            | +/-1,50                 | +40/-0             |

# SHEETS 2000X1000 MM.

| ◆ Thickness MM. | ◆ Thickness Tolerance MM. | ◆ Size Tolerance MM. |
|-----------------|---------------------------|----------------------|
| 1               | +/-0,050                  | +60/-0               |
| 1,5             | +/-0,050                  | +60/-0               |
| 2               | +/-0,100                  | +60/-0               |
| 2,5             | +/-0,125                  | +60/-0               |
| 3               | +/-0,150                  | +60/-0               |
| 4               | +/-0,40                   | +60/-0               |
| 4,5             | +/-0,40                   | +60/-0               |
| 5               | +/-0,40                   | +60/-0               |
| 6               | +/-0,40                   | +60/-0               |
| 8               | +/-0,60                   | +60/-0               |
| 10              | +/-0,60                   | +60/-0               |
| 12              | +/-1,00                   | +60/-0               |
| 15              | +/-1,00                   | +60/-0               |
| 20              | +/-1,00                   | +60/-0               |
| 25              | +/-1,00                   | +60/-0               |
| 30              | +/-1,50                   | +60/-0               |
| 35              | +/-1,50                   | +60/-0               |
| 40              | +/-1,50                   | +60/-0               |
| 45              | +/-1,50                   | +60/-0               |
| 50              | +/-1,50                   | +60/-0               |
| 60              | +/-1,50                   | +60/-0               |
| 70              | +/-1,50                   | +60/-0               |
| 80              | +/-1,50                   | +60/-0               |